CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRSUBD20201700Address:3521 SW MARKET ST, LEES SUMMIT, MO 640823500 SW MARKET ST, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Water Line - Construction Inspection		Tom Taylor	Passed	Friday, December 11, 2020	
Informational:					
1	Misc	Reinkie Excavating layer a fittings and backfilled all	approx. 150 LF of 8" waterlir applicable areas.	ne with all necessary	
Informational:					
2	Misc	•	ne contractor pot holed area taps for Wednesday night shut.	-	
Informational:					
3	Misc	On Wednesday, 9-02-2020 approx 50 LF of 6" Waterli	Reike installed the water ine.	main "T" and placed	
Informat	ional:				
4	Misc	-	. Contractor completed ma across street. And barricade		
Informational:					
5	Misc	-	contractor Placed high earl CG-I curbing. Contractor als traffic.	-	
Informational:		. ,			
6	Misc	On Tuesday, 10-13-2020. ⁻ west of the vault that was	The contractor laid approx. s installed as well.	30 LF of 6" waterline just	
Informational:					
7	Misc	On Monday, 10-19-2020. I	performed a water line ins	pection on the 2"	

		domestic and 4" cooper water line coming from the main. All inspections passed city standards.
Informatio	onal:	
8	Misc	On 10-13-2020 Reike Construction installed Vault for back flow valve and installed (1) fire line valve . Also installed 30LF of 6" pvc pipe w/ fittings.
Informatio	onal:	
9	Misc	On Thursday, 10-15-2020. Reinke Construction installed (1) fire hydrant in the parking lot and also installed the Backflow valves with 60 LF of 6" plastic pipe. (1) thrust block was poured as well.
Informatio	onal:	
10	Misc	On Friday 10-16-2020. John Jackson performed a Hydrostatic pressure test for the fire line. Presure test passed with 200 LB. of pressure for 2 hours.

Comments: