CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20202304

Address: 1519 SW ARBOR FALLS DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Robb Popp Failed Friday, January 29,

Residential 2021

Corrective Action Required:

1 Miscellaneous -Maintain gravel filter

Correction -Complete exterior sheathing nailing pattern at back of house-Southeast side

bottom perimeter

-Seal fire block at soffit line in garage at 2" DWV -Provide midpoint strap on all DWV 2" and smaller

-Provide engineered correction for trusses and hangers nailed to blocks at

owner's entry

-Missing (4) 2x4 at Home office

-Connect 2x6 exterior corner studs at stairway-connect both exterior studs

12" OC

Comments: