CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20203857

Address: 2358 SW HICKORY LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - John Morris Failed Monday, March 01,

Residential 2021

Corrective Action Required:

1 Misc

- -Nail exterior sheathing per plan throughout
- -Studs bored over 40% in exterior wall at garage by electrical panel, provide $\,$

stud shoe

- -Nail all corners and intersecting walls per code
- -complete electrical installation from stud repair in dining room

Comments: