

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20203523
Address: 1520 SW ARBOR VALLEY DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Patrick Schonfeldt	Failed	Monday, March 01, 2021

Corrective Action Required:

1	Misc	-Fireblock top plate penetrations at laundry dbl wall - see DWV, unused bore, and dryer vent penetration -Fireblock deadspace at stairs - 1st floor to attic space -Install backdoor -LIB bracing, all locations per plans - max 16" oc stud spacing at lib braced walls -Joist hanger required at joist to stair rim connection in basement, over 4'
---	------	---

Comments: