CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSITE20193581 Address: 2001 NW SHAMROCK AVE, Unit:IR, LEES SUMMIT, MO 640812001 NW SHAMROCK AVE, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Site Visit		Ronald Paynter	Partial	Friday, March 19, 2021
Informational:				
1	Misc		xiom. Still waiting to hear f flow vault. Put in a call to	
Informational:				
2	Misc	Bair Excavating started for the correct riser for the de	rming the detention basin t etention box.RP 6-17-20	oday. Still waiting on
Corrective Action Required:				
3	Misc		ding the detention basin. D the bottom section of ponc red on site. RP 6-18-20	
Correctiv	e Action Required:			
4	Misc	our approved product list that it might be ok, but it Excavating said they are g	02 geo grid on site for the p . Informed Shane from Bair needs to be approved by th oing to switch to LBO 302 ge y engineer before it can be	and Norm from Axiom e city engineer. Bair eo grid, which still needs
Informational:				p
5	Misc		ding the parking lot. Plan is t and grout storm boxes. D 9-2-20	
Informational:				

6	Misc	Bottoroff formed and poured concrete sections of parking lot for the ADA drop off points. They also formed up the dumpster pad and are waiting on concrete to pour. RP 9-24-20				
Informatio	Informational:					
7	Misc	Bottoroff poured the footings for the dumpster pad yesterday and form and poured the dumpster pad today. They are planning on laying base asphalt tomorrow. RP 9-25-20				
Informational:						
8	Misc	Stopped and talked with Norm today. Crews still working on the building. RP 11-2-20				
Informational:						
9	Misc	Talked with Norm about the detention basin again. He agrees that something isn't right and he will have Larry Bair Excavating find out what is wrong with the drainage. RP 11-9-20				
Informational:						
10	Misc	Landscapers have sodded most of the site. I talked with Rusty about cleaning up some weeds and dirt clumps they left by the fire station. No progress on replacing the sidewalk yet. Norm did call Bottoroff last week to remind them. RP 11-24-20				
Informational:						
11	Misc	Bair Excavating removed silt fencing and downed trees along the south perimeter. The also removed any vegetation in the area, so I had them place wattles to eliminate any erosion issues. RP 12-11-20				
Informational:						
12	Misc	Met with Don and Lief from Bair Excavating to have a precon about what still needs done with the detention basin. RP 2-23-21				
Informational:						
13	Misc	Talked with Norm from Axiom. They are ok for a TCO, but they need to fix the drainage issue and establish 70% vegetation before they can receive a full CO. RP 2-26-21				
Informational:						
14	Misc	Met with James from Axiom to discuss the detention basin. Still have a small section of standing water east of the outlet structure. James's said Bair Excavating is suppose to be there to make changes to fix that problem today. RP 3-2-21				
Informational:						
15	Misc	Bair Excavating is working on the correct heights of the berms and Axiom dug out little trenches around the field inlet and outflow structure. They filled the trenches up with rip rap, but am not sure if it's functionable? Steve Robbins is going to look at it with me tomorrow. RP 3-3-21				
Informational:						
16	Misc	Checked on the detention basin, it's currently holding water from last night's storm. Will monitor the drainage process. RP 3-11-21				
Informational:						
17	Misc	All water has drained from the detention basin in 24 hrs. RP 3-12-21				
Corrective Action Required:						
18	Misc	Large basin is almost done draining this weeks rainfall. Small basin is still full of water. Small basin needs to be elevated to assist in draining. RP 3-19-21				

Comments: