CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20203428

Address: 4405 SW TANZANITE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Patrick Schonfeldt Failed Wednesday, March 24,

Residential 2021

Corrective Action Required:

1 Misc -Sidewalk required -Final grade and sod

-Gutters, downspouts, splash blocks and sump pump discharge extension

required

-seal all penetrations in siding, seal along top of AC disconnect and meter can

-Guardrail required at front porch, more than 30" from grade

-Install cooktop and hood in kitchen

-Dishwasher discharge line should go high and then low for disposal $% \left\{ 1,2,\ldots,n\right\}$

connection

-High/low vents required at mechanical room for combustion air

-Clip set screw on anti siphon on spigot at main water line in basement

-Flue b vent at furnace requires 1" clearance from combustibles, secure UFER ground wire off b vent

-Hot water heater blowout discharge line requires termination above floor not less than 2 times the pipe diameter, maximum 6"

-Install lights at master bath vanity

-Tempered glass required at window in master bath shower

Comments:	
------------------	--