## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20192096 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Miscellaneous Inspection	Michael Harkins	Failed	Thursday, March 25, 2021
Corrective Action Required:			
1 Misc	<ul> <li>PROVIDE GFCI PROTECTINEC 210.8 (D) -</li> <li>PROVIDE SECONDARY LOSECTION 7 1406 (B) )</li> <li>ABOVE ALL UNITS 444 TH</li> <li>444 ANTI TIP DEVICE RAI</li> <li>445 GFCI EACH SIDE OF HMISSING -</li> <li>446 DECK RAIL MISSING,</li> <li>447 -</li> <li>448 GUARDS SHALL NOT SPHERE 4" IN DIAMETER (</li> <li>449 FIRE CAULK LINE SET</li> <li>450 -</li> <li>451 FIRE CAULK CEILING</li> </ul>	NGE - RANGE AND ISLAND WON'T FIRE CAULK LINE SET MECH HAVE OPENINGS THAT ALLO PER 2018 IBC 1015.4 ) TS MECH ROOM CEILING -	ER OUTLETS PER ( 2017 S ( LEE"S SUMMIT RESET, DECK RAIL ROOM CEILING - DW PASSAGE OF A

- 455-

- 456 DECK RAILING 4" SPHERE SHALL NOT PASS -

- 457 -

- 458 GFCI BEDROOM BATH WON'T RESET -

- 459 -

**Comments:**