CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204752 Address: 2045 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Erosion Control		Michael Harkins	Failed	Tuesday, April 06, 2021
Corrective Action Required:				
1	DCM2 ESC	DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED. - PROVIDE ADDRESS -		
	DEFICIENT			
	INSTALLATION			
		- MAINTAIN SILT FENCE -		
		- MAINTAIN GRAVEL FILTE	R -	
Corrective Action Required:				
2	DCM2 ESC	- MAINTAIN SILT FENCE -		
	DEFICIENT			
	INSTALLATION	DEFICIENT EROSION CONT	ROL INSTALLATION. NO FUI	RTHER INSPECTIONS
		UNTIL ADEQUATE EROSIO	N CONTROL PROVIDED.	

Comments: