## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20191614

Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Robb Popp Partial Wednesday, April 07,

Commercial 2021

Informational:

1 THIRD FLOOR —AREAS APPROVED—

\*\*\*BUIDING C\*\*\*

PRE ROCK:

3019-3031 MECHANICAL ROOM WALLS AND BEHIND SHOWERS

ROOMS:3031, 3030, 3029, 3028, 3027, 3026, 3025, 3024, 3022, 3019, 3020

-STAIRWELL WALLS AND CEILING

\*\*\*BUILDING A\*\*\*

PRE ROCK:

3003-3016 MECHANICAL ROOM WALLS, BEHIND SHOWERS

ROOMS: 3004, 3006, 3008, 3010, 3012, 3014, 3016

Informational:

2 SECOND FLOOR —AREAS APPROVED—

\*\*\*BUILDING C\*\*\*

PRE ROCK:

OK TO ROCK WALLS OF MECHANICAL ROOMS 2020-2031

OK TO ROCK CORRIDOOR WALLS FOR SOFFIT AND INSTALL RC AT CEILING

Informational:

3 FIRST FLOOR -AREAS APPROVED-

\*\*MCAL BUILDING\*\*

PRE ROCK:

MECHANICAL ROOM 165 NORTH WALL

Corrective Action Required:

Miscellaneous

3021-COMPLETE RIDGE VENT OR ROOFING

Correction

-SEAL LINE SET PENETRATIONS IN DRAFT STOP THROUGHOUT-CHECK LINE SET

PENETRATIONS AFTER INSTALLATION

-3020- MISSING ROOF BOOT AT VENT-CHECK WITH RC INSPECTION

## **Comments:**