CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204442

Address: 2009 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Failed Friday, April 16, 2021

Residential

Corrective Action Required:

1 Miscellaneous House not ready for inspection this list was made without looking at plans or

Correction truss package list subject to change after trade make corrections

complete below list and call for reinspect

Fire blocking fireplace

Seal penetration bottom plate master water closet

Expose H2.5s deck

Provide H2.5 or truss screws garage Provide truss screws double girder truss

Provide 1 1/2 bearing girder truss at single car both ends

Fire blocking at b vent laundry

Fire stopping at beams

Over bored joist above basement stairs

Provide anchor bolts within 12" of plate breaks basement

Support gas line per code

Support DWV every 4' NE bed basement Seal upward penetrations throughout !!!!! Provide double joist hangers deck at fireplace

Strap header at windows under deck Strap Corner at beam under deck Tighten anchor bolts throughout Provide truss screws above front door
Tie top plate together above front door
Secure gas line fire place
Support header covered deck (remove plywood expose king studs)
Nail corner studs per code
Roof vents partially covered
Provide 5/8 anchor bolts PFH portal garage
Fire blocking basement furr outs
Comply with fire resistance rating for exterior wall/projections less than 5'
from property line (see 2018 IRC R302.1 (1)

Comments: