CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20203582

Address: 2312 SW CHASE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection -

Residential

Patrick Schonfeldt

Failed

Monday, April 26, 2021

Corrective Action Required:

1 Misc

- **UPLOAD ALL ENGINEER REPORTS TO PERMIT**
- -Suspended slab at front stoop poured without inspection, submit engineer report -garage portal PFH detail shows triple bottom plate with 5/8" anchor bolt with 2" x 2" x 3/16" plate washer, R602.10.6.2, see detail on page S-2.0 in plans, unable to determine, sheathing has been attached on interior of garage portal
- -pan off at cantilever in garage at sgl car
- -fireblock DWV chase at garage, see E side garage entry for bump out for DWV, fireblock at bump out
- -security blocking at exterior doors
- -Joists at W8x31 beam in breakfast required to bear 3" on beam at end of joist, with lateral restraint R502.7
- -Joist hanger required at tail joist to header connection at rear covered patio, joist over 4'
- -(2) 1 3/4" x 9 1/2" lvl at covered patio rear center, middle post per plans
- -(2) 2x12 upset at 2nd floor baths and bed#4 per plans
- -complete gas line install, see ward flex at NW corner of basement, complete line run with shutoff

Comments: