

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20203786
Address: 153 NW CARSON DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	John Morris	Failed	Thursday, May 13, 2021

Corrective Action Required:
1 Misc

-Penetrations in floor joists shall not be closer than 2 inches to the top or bottom of the member, or to any other hole located in the member. 5 locations south foundation wall, 1 location in hall at bed 3 entrance, bed 3 at smoke alarm, two locations bed three closet, Three locations above bed three window, 2 locations above rec room. Comply with section 502.8.1 or provide engineered solution for repair

Ok to insulate

Comments: