

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Miscellaneous Inspection	Mark Harding	Partial	Thursday, May 13, 2021

Corrective Action Required:

1	Misc	4th floor corrections 5/13/21 405locked 426 locked 406-427-424-408-fire caulk hole in ceiling furnace room. 425-painted head in furnace room. Storage ok 423- dishwasher breaker not working. 421-porch railing. 1-4A panel room, open panel for label. Correct fire damper control in wall over door. Inspected and OK -404 ,407,409,410,420,419,422,428,429
---	------	--

Corrective Action Required:

2	FOURTH FLOOR	Pre final -units approved: 444-459,431- 443 ,460-465. , 425A,421A,424B, Corridor 412 5/13/21 Following
---	--------------	---

		"B" side
		Ok-429,428,404 ,407,422,409,420,419,410,
Corrective Action Required:		
3	THIRD FLOOR	3/29/21
		339 ,340 ,341 ,342 ,343;345, 346-365;366, 367;
		345,344. 331-338,
		324B 332,333,
Corrective Action Required:		
4	SECOND FLOOR	4/8/21 4/9/21
		239-253; 255 -263 ;265-267;221A,230,231,232,234,235,236,238,
Corrective Action Required:		
5	FIRST FLOOR	4/12/21
		119; 122-138;
		117 ok
		118 ok
		119 ok
		120 ok
		121 ok
		120A ok
		122 ok
		120A ok
		230 ok
		231 ok
		232 ok
		233 ok
		234 ok
		235 ok
		236 ok
		237 ok
		238 ok
		225A ok
		220A ok
Corrective Action Required:		
6	THE FOLLOWING	Pre Final areas approved are the following;
	AREAS ARE	see sepertate floor levels.
	APPROVED	*.:

Comments: