

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204988
Address: 310 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Michael Harkins	Failed	Friday, May 14, 2021

Corrective Action Required:

1	Miscellaneous Correction	-Frame front covered porch per code (full length ridge beam, rafter ties, collar ties, hangers, rafter to top plate connection, etc.) or use designed trusses on approved plans (2 x 8 ridge per engineer letter. FRAMED 2 x 6 ridge short of fascia) Ok to insulate Do not cover porch until re inspect
---	--------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Comments: