

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20210293  
Address: 3022 NW THOREAU PL, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Erosion Control</b>	John Morris	Failed	Tuesday, May 18, 2021

Corrective Action Required:

1	Misc	-Erosion control methods require continuous maintenance. Repair damaged sections within 48 hours -Immediate street cleanup required -remove debris from stormwater inlet
---	------	--

no further inspections until issues are resolved

**Comments:**