

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Miscellaneous Inspection	Michael Harkins	Partial	Tuesday, May 18, 2021

Corrective Action Required:

1 Misc

Inspected and OK

-404 , 404A, 406A,406B,408A,407,409,410,410A,413, 414,415,,
420,419,422,428,429, 401, 402, 403, 405, 406, 408, 411, 412, 416, 417,418,
421, 423, 424, 425, 426, 427

Corrective Action Required:

2 FOURTH FLOOR

Pre final -units approved:

444-459,431- 443 ,460-465.

, 425A,421A,424B,

Corridor 412

5/13/21

Following

"B" side

Inspected 401- 412; 416,417, 419-429;

Corrective Action Required:

3 THIRD FLOOR

3/29/21

331-367;

324B

5/17/21

301,303,304,305,306,307,308,309,310,312,313,315,316,318,319,321,322,
323,324,326,327,328,329, APPROVED

302 REPAIR/REPLACE GFCI BATH NEAR LAUNDRY
325 PROVIDE ANTI TIP DEVICE RANGE
311 BATH EXHAUST, LAUNDRY SPRINKLER ESCUTCHEON
314 NO ACCESS
317 SECURE GFCI BOX DISHWASHER UNDER SINK
320 DECK RAIL OVER 4"
PROVIDE ROOM # SIGNS IN CORRIDOR

Corrective Action Required:

4 SECOND FLOOR

4/8/21 4/9/21
; 255 -263 ;265-267;221A,230-253;
225A ok
220A ok

Corrective Action Required:

5 FIRST FLOOR

4/12/21
117--138;

120A ok

Corrective Action Required:

6 THE FOLLOWING
AREAS ARE
APPROVED

Pre Final areas approved are the following;
see sepertate floor levels.
*:

Comments: