## CITY OF LEE'S SUMMIT

## Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20204780

Address: 2025 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Failed Wednesday, May 19,

Residential 2021

Corrective Action Required:

1 Misc Note only for ALL-Rough

R302-2018 IRC

At garage wall needs to be rated as per section 302 both sides.

Tighten anchor bolts basement

Provide anchor bolts within 12" of plate break west basement wall Provide 3 studs of braced walls east & west corners of basement

Provide CS-PF nailing pattern & straps per plan Dining room & SGD dining room

& basement

Provide (2) 2 x 10 headers above rear basement windows

Provide 1 1/2 bearing deck beam

Solid block top plate to roof deck garage & complete west wall

Provide 5/8 anchor bolts PFH portal frame garage

Anchor bolts shall be in middle 1/3 of width of plate garage

Replace LIB rear wall garage

Seal electrical penetration top plate foyer Land conductor in a box pantry ceiling

Provide roof boots vent to roof master water closet

Seal fire blocking fireplace

Provide (2) 11 1/4 LVLs corner to corner per plan great room

Missing truss lock screw GT foyer/ garage

Expose trusses porch & patio

_					_	
Co	m	m	•	n	tc	٠
LU			_		LS	