



# LEE'S SUMMIT MISSOURI



## FIRE DEPARTMENT

### NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

CHANGES

<b>BUSINESS NAME</b>	STREETS OF WEST PRYOR - BIBIBOP ASIAN GRILL		
<b>ADDRESS</b>	2050 NW LOWENSTEIN DR, Unit:E, LEES SUMMIT, MO 64081		
<b>OWNER/OPERATOR NAME</b>	JL Moore General Contractor:	<b>TELEPHONE</b>	(440) 236-3589
<b>ADDRESS</b>	27102 Royalton Road Columbia Station, OH 44028 Primary: (440) 236-3589 Cell: <NO CELL PHONE>		

### EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1. _____	_____
2. _____	_____
3. _____	_____
4. _____	_____

### LOSS REDUCTION TYPE

<input type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: A-2	Map#:	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT #

### LOSS REDUCTION NARRATIVE

NO VIOLATIONS NOTED

ALL VIOLATIONS RESOLVED

Last Inspection      1st Inspection      2nd Inspection      3rd Inspection      4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Craig Hill	Not Ready	Monday, May 10, 2021
Occupancy Inspection - Fire	Craig Hill	Failed	Thursday, May 20, 2021
Alternate Protection Systems	Craig Hill	Passed	Thursday, May 20, 2021

**Inspection**

DATE OF REPORT

May 20, 2021

INSPECTOR

Craig Hill

PREVENTION FOLLOW-UP  
REQUIRED?

**Yes**     **No**

RESPONSIBLE SIGNATURE