CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210058

Address: 2054 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Failed Wednesday, May 26,

Residential 2021

Corrective Action Required:

1 Misc Install missing windows

Tyvek tape nail penetrations @ garage portal framing

Set nail joist hanger above arch dining

Solid block exterior walls at top plate & nail sheathing per code

Tighten 5/8 anchor bolts garage portal framing Provide joist hanger valley rafter to beam dining

Tighten anchor bolts basement

Fire Block Duct in dead space near wet bar

Seal NM at plenum exercise room

Seal NM at top plate exercise room east wall

Anchor bolts shall be in middle 1/3 of width of plate behind patio door

Seal bore at top plate furr out bed #3 closet schedule electrical service & gas service if ready

Comments: