

Inspection Summary

Permit #: PRSUBD20204418, Development - Subdivision
Napa Valley 2nd plat - retention basin conversion
Address: 1604 SW NAPA VALLEY DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

| Inspection: | Inspector: | Outcome: | Date: |
|---|--|----------|------------------------|
| Storm Sewer Construction Inspection | John DiMauro | Passed | Tuesday, June 01, 2021 |
| Erosion Sediment Control (ESC) Inspection | John DiMauro | Partial | Tuesday, June 01, 2021 |
| Informational | | | |
| 1 | Silt fence needs to be removed from around the basin when vegetation has been fully established. | | |
| ESC - (Vegetation/Ground Cover) | John DiMauro | Passed | Tuesday, June 01, 2021 |
| Storm Sewer Construction Inspection | John DiMauro | Passed | Tuesday, June 01, 2021 |
| As Built | Steve Robbins | Passed | Tuesday, June 01, 2021 |

Comments: