CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20211979 516 SE DAVID RD, LEES SUMMIT, MO 64082 Address:

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Plot Plan Inspection	Mark Harding	Failed	Tuesday, June 08, 2021
Corrective Action Required:			
1 Misc	The submitted plot plan is below the MBOE and below the MDP. Before we can		

1

The submitted plot plan is below the MBOE and below the MDP. Before we can lift the Stop Construction order the plot plan and foundation wall need to be corrected. This issue was communicated with you by Robb Popp prior to pouring the foundation wall by phone and email on 5/19/2021.

Comments: