CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204860 Address: 325 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Michael Harkins	Failed	Tuesday, June 29, 2021

Corrective Action Required:

1	Miscellaneous Correction	Provide anchor bolts SCH 40 columns at wet bar basement Tighten anchor bolts basement Provide nut & washer anchor bolts basement Bath near missing window
		Provide anchor bolts near missing basement window anchor bolts shall be in middle 1/3 of width of plate
		Fire block vertical to horizontal fitness room
		Fire block vertical to horizontal wrapping room
		Address Ballon frame 2x6 wall at stairway per plan
		Address I beam great room plans show (3) 24" LVLs
Seal bottom plate penetrations dining room		-
		Seal low volt penetrations at plenum dining room master
		Seal bottom plate penetrations dining room / master
		Seal bottom plate penetration master north wall
		Provide roof boots VTR throughout
		Nail studs under strut master closet
		Seal bottom plate penetration behind front door
		Seal low volt bottom plate penetrations bed 2 / office
		Tighten anchor bolts single car garage door

Comments: