CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204524

Address: 2037 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection -

Residential

Michael Harkins

Not Ready

Friday, July 16, 2021

Corrective Action Required:

1 Misc

FRAMING:

- -Fb space adjacent to refrigerator&shower from roof (Stand in front of tub and look up)
- -Strap rear dining CSPF walls headers and nail exterior siding per code. Look at plan for details
- -Provide full bearing for both plies of the porch (2)2x10 beam. Complete walls
- -Provide continuous sheathing for rear great room wall to top plate (solid block & nail per code)
- -Nail sheathing to studs at master bedroom/deck wall
- -Tie down GT A04 to garage/closet wall
- -Anchor garage sill plate within 12" of break; min 2 anchors per short plate
- -Brace C and A trusses per plan
- -Fb basement wall vertically at ten ft or less interval; fb both basement closet walls from fur down ceiling space and soffit (seal gaps)
- -Nail all deck joist hangers; lag ledger board to rim band; install middle support post for deck beam.

ELECTRICAL:

- -Re-install electrical in front bedroom and master bedroom
- -Seal all wiring penetrations of return air space
- -Secure NM cable at max 4.5 ft and min 1.25" from stud surface at corner of rear great room wall and slide door wall

**DO NOT INSULATE
NOT READY 7/14/21
: DO NOT INSULATE 7/14/21

Comments: