

July 19, 2021

Summit Homes 120 SE 30<sup>th</sup> St. Lee's Summit, MO 64082

## RE: Field Issue of non continuous header for CS-PF panel Lot #65 Reserve at Stoney Creek – 1425 SW Georgetown Dr. Lee's Summit, MO 64082 – Permit # PRRES20210350

This letter addresses the non continuous (2) 1-3/4" x 11-1/4" LVL 3100 Fb VersaLam header for CS-PF portal frame in the great room.

## Revision shall be as follows:

• Install a 24" length of CS-16 coil strap centered over header at each stud pack in between the windows and at the ends of the windows. Install with fasteners per manunfacturer's specs.

Sincerely,

4

Bradley Huxol, PE

