

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20204957  
Address: 2041 NW ASHURST DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Robb Popp	Failed	Wednesday, July 21, 2021

Corrective Action Required:

1	Misc	Builder requested garage portal wall framing and rear patio roof framing only: -Nail the garage PFH wall sheathing to sill plate with 8d @ 3" oc
---	------	---

**\*\*Please do not cut out too much of the bottom garage PFH wall plates**

Corrective Action Required:

2	Miscellaneous Correction	Solid block sheathing breaks and nail per plan/ per code ( no staples ) sheets S1.0 ( rear of single car garage / bed #2 no 8D nails all staples ) Exterior bracing WSP shall be not less than 48" total at end of braced wall line 6/30/21 Nail sheathing throughout per code / per plan Sheet S1.0 8D nails no staples ( !not done ) :BED #3 CS WSP NAILING PER PLAN PER CODE 6/16/21 not done ) Nail sheathing per plan SGD at deck 8D nails no staples ( see staples no nails in header 6/16/21)
---	--------------------------	---

: NOT READY / DO NOT ISULATE :

Michael Harkins 07/14/2021 12:54 PM

Michael Harkins 07/16/2021 1:52 PM

**Comments:**