# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street

Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRRES20202309

Address: 1717 SW 27TH ST, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Khanh Nguyen Failed Thursday, July 22, 2021

Residential

#### Corrective Action Required:

1 Misc -Strap header and nail sheathing of garage PFH wall per plan

- -Garage ceiling joist notched more than 25%
- -Fb double stud wall near refrigerator
- -Expose deck roof ridge support framing
- -Secure CSST gas line every 32" inside fireplace space
- -Complete fireplace flue through roof; complete framing and secure fireplace to framing
- -Provide roof purlin above master area
- -Move master closet roof support to bearing wall
- -Studs not continuous full height at front bedroom gable wall
- -Provide a floor receptacle at foyer guardrail for foyer larger than 60 sq ft
- -Fb all basement wall space from fur down ceiling space and joist space; fb wall vertically at max ten ft interval, including space above windows
- -Complete basement bedroom closet ceiling framing and fire block as required
- -Have engineer address over-notched joist above front basement bedroom
- -Security blocking for basement walkout door
- -Tighten all anchor nuts
- -Install a wall receptacle at wall space near wet bar countertop
- -Provide brace walls per A/4 detail
- -Brace interior walls per plan

### \*\*OK TO INSULATE

**Comments:**