CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210901

Address: 123 NW JOSHUA DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Not Ready Thursday, August 05,

Residential 2021

Corrective Action Required:

1 Miscellaneous GARAGE PORTAL FRAME ONLY

Correction Nail sheathing per code no staples

Fasten top plate to header with two rows 16D sinkers 3" OC

Provide header to jack stud straps per plan

Nail hold downs

Spliced edges in sheathing shall occur over and be nailed to common blocking within middle 24" of wall mud height one row of 3" OC nailing is required in

each panel edge

Per plan details 12 sheet S2.0

Corrective Action Required:

2 Miscellaneous : Garage portal frame, Ft porch & patio ONLY :

Correction NO PLANS ON SITE

PFH portal frame

Nail sheathing per code (no staples)

Nail top plate to header w/ 16d sinkers 3" OC

Patio covered unable to see trusses

Front porch covered unable to see trusses

Comments: