CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20190654

Informational:

Misc

6

Address: 2030 NW OBRIEN RD, LEES SUMMIT, MO 640812020 NW OBRIEN RD, LEES SUMMIT, MO 64081500

NW PRYOR RD, LEES SUMMIT, MO 64081450 NW PRYOR RD, LEES SUMMIT, MO 64081

K & G Striping was on site laying out the new crosswalks for Pryor and O'Brien

intersection. They will also be removing the old crosswalks. They installed

new crosswalks, stop bars and turn lane arrows. RP 10-19-20

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date: Site Visit **Ronald Paynter** Failed Thursday, August 05, 2021 Informational: 1 Misc Talked with Brian from Randy Spalding. They are re-grading the roadways on Shamrock, Grady and Joshua. Plan is to let them bake a couple more days before trying the proof-roll. RP 6-8-20 Informational: 2 Misc Met Brad from JK Concrete on site. Answered questions concerning curb and sump inlets. RP 6-17-20 Informational: 3 Misc Superior Bowen is attempting to clean the asphalt off of the concrete section of Shamrock. I will have Public Works check its status for approval on Monday. RP 8-1-20 Informational: The Water Dept installed construction taps for the water main on Joshua and Misc Ashurst. RP 9-25-20 Informational: Brian's crew from Spalding has been grading the west side of Pryor and Misc O'Brien for the sidewalk and ADA ramps. RP 9-29-20

Informational:

7 Misc Brett from K&G Striping was laying out street lanes on Pryor and O'Brien

intersection. I had Nick Lightner from Public Works help me with this

installation. RP 10-20-20

Informational:

8 Misc Talked with Capital Electric, who was on site installing the last ped crossing

signal. There is a old concrete base that still needs to be removed. Capital is going to find out if it was their old ped signal base. K&G Striping finished applying the double yellow lines on O'Brien. They also corrected the

orientation of the street signs on Shamrock. RP 11-2-20

Informational:

9 Misc Walking the subdivision, compiling items that need to repaired or corrected

for the punch list. RP 11-16-20

Informational:

10 Misc Redford crew out working on damaged stop sign and adjusting manholes.

Teague Electric is still working on power installation and trying to keep the

roadway clean. RP 11-24-20

Informational:

11 Misc Met with Aree and Heath from Redford Construction concerning cleaning out

storm end sections that have become buried. Heath found solid rock under the buried end section. Solid rock needs to be removed and replaced with

rip rap. RP 12-1-20

Informational:

12 Misc Checked on punch list items. Concrete work is all the is remaining from

original punch list. RP 12-11-20

Informational:

13 Misc Checked on punch list items. Concrete work is all the is remaining from

original punch list. RP 12-11-20

Informational:

14 Misc Checked on punch list items. Concrete work is all the is remaining from

original punch list. RP 12-11-20

Informational:

15 Misc Only items remaining from the punch list is vegetation for Kaylea Ct and

maintenance of all erosion control devices. RP 4-30-21

Corrective Action Required:

16 Misc Curb inlets are full of silt on Ambersham. Please clean out and replace gutter

buddies. RP 5-24-21

Informational:

17 Misc Redford Construction removed sunken asphalt and curbing at 1 of the 3 areas

on Ambersham. The poured the curbing and all but 2 inches of the hole with

KCMMB concrete. RP 6-9-21

Informational:

18 Misc JK Concrete replaced curbing at 2nd and 3rd sunken areas of roadway on

Ambersham by Killarney. RP 7-22-21

Informational:

19 Misc JK Concrete replaced the ADA ramp at Ambersham and Killarney. Redford

Construction back filled the 2nd and 3rd sink holes with 4K KCMMB mix. RP

7-26-21

Corrective Action Required:

20 Misc Concrete was spilled and dried in the roadway at Ashurst and Kaylea. RP

Comments: