David P. Ainsworth, P.E. 1200 NW Hearnes Ave, Blue Springs, MO 64015 Cell Phone: 816-682-2093

Email: dainsworth@chelepis.com

May 20, 2021

Dave Richards
Dave Richards Homebuilding, Inc.
P.O. Box 1325
Blue Springs, MO 64013

Re: 1101 NE Goshen Dr Monticello Lot 83 Lee's Summit, MO Deck support at corner of overhang

Dear Mr. Richards:

On May 20, 2021, I inspected the support of the deck at the corner where the deck meets the overhang at the rear of the house. There is a 6"x6" structural timber column at the corner that provides both deck support and also supports stacked studs above that ultimately support the corner of the roof.

This framing as installed is adequate to support all imposed loads.

Cordially,

David P. Ainsworth, P.E.

PANA AMERICAN AMERICA