

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210948
Address: 306 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Michael Harkins	Failed	Friday, August 06, 2021

Informational:

1	Misc	GARAGE PFH PORTAL FRAME OK TO COVER FRONT PORCH OK TO COVER COVERED DECK OK TO COVER : ONLY ABOVE ITEMS INSPECTED :
---	------	--

Corrective Action Required:

2	Miscellaneous Correction	Fire block (insulate) beam pockets Seal Upward penetrations above service panel (seal vertical to horizontal at top plate fire blocking at furr out leave exposed for inspection) Install tubs Nail exterior sheathing per code : OK TO INSULATE :
---	--------------------------	--

Comments: