

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210050
Address: 338 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Michael Harkins	Failed	Thursday, August 12, 2021

Corrective Action Required:

1	Miscellaneous Correction	Provide anchor bolts end of plate garage Provide solid security blocking patio door Seal fire blocking fireplace lid Address rafters la lqnding on multiple blocks (Skeens letter is for different house) Address cut joist coat closet Address cut joist north storage basement Structural straps DWV bearing walls 16 gage and 1.5 in wide with 8 10d nails each side (R602.6.1 2018 IRC) Seal upward penetrations bed #4 Provide collar ties per plan Provide 3.5 SCH 40 columns B & D per plan Provide anchor bolts SCH 40 columns Provide shield / gutter DWV above service panel & cap off Nail exterior sheathing per code
---	--------------------------	---

Informational:
2 Misc

COURTESY INSPECTION MET WITH RICK TO LOOK AT ITEMS ON INSPECTION REPORT

Comments: