

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210252
Address: 138 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Michael Harkins	Failed	Wednesday, August 18, 2021

Corrective Action Required:

1	Miscellaneous Correction	Address spliced hip & valley above master closet Provide CS-PF braced wall method at SGD deck Seal upward penetrations DWV butlers panty (no) Seal vertical to horizontal fire blocking at top plate furr out basement (!not done) Provide vertical fire blocking every 10' basement furr out (seal @ bed # 3) Drop ceiling bed #4 closet at beam (seal gap at soffit) Nail exterior wall sheathing per code
---	--------------------------	---

Comments: