

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211352
Address: 4824 NE JAMESTOWN DR, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Steve Robbins	Failed	Thursday, August 19, 2021

Corrective Action Required:

1	DCM2 ESC DEFICIENT INSTALLATION	DEFICIENT EROSION CONTROL INSTALLATION. SHALL RESTORE EROSION CONTROL ALONG THE STREET, AND CLEAN UP THE STREET
		NO FURTHER INSPECTIONS UNTIL ADEQUATE EROSION CONTROL PROVIDED.

Corrective Action Required:

2	Misc	Field inlet in back of property is clogged up due to excessive silt build up. The water cannot drain into the inlet and is causing the home at 4828 Jamestown to have water backing up into their yard. Please take care of this right away. No inspections until this is taken care of. We will check this next friday on 8/20 and if no progress is made we will begin stop work order process.
---	------	---

Comments: