## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRSUBD20211138

Address: 1201 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection:                            |               | Inspector:  | Outcome:  | Date:                       |
|--|---------------|---|---|-----------------------------|
| Storm Sewer Construction<br>Inspection |               | Ronald Paynter  | Partial   | Tuesday, August 24,<br>2021 |
| Informational:                         |               |   |   |                             |
| 1                                      | Misc          | Installed structure 200, 201. The end structure on 201 was installed. Pipe is being laid toward strucure 202.   |   |                             |
| Informational:                         |               |   |   |                             |
| 2                                      | Misc          | they laid 100 feet of 54 inch RCP pipe. They also set junction box 202 and curb inlet 203. They need to move the water main before they can connect to curb inlet 204. RP 8-11-21 |   |                             |
| Informational:                         |               |   |   |                             |
| 3                                      | Misc          | They poured collars for storm structures 200, 201, 202 and 203, then back filled all storm lines. RP 8-12-21  |   |                             |
| Informational:                         |               |   |   |                             |
| 4                                      | Misc          | They laid 275 feet of 18 inch HDPE storm pipe and set curb inlets 302, 303 and junction box 304. Plans don't call for a 301 structure. RP 8-16-21                                 |   |                             |
| Informational:                         |               |   |   |                             |
| 5                                      | Misc          | They laid 120 feet of 18 in RP 8-17-21  | ch HDPE storm pipe. They a  | also set field inlet 305.   |
| Informational:                         |               |   |   |                             |
| 6<br>Informati                         | Misc<br>onal: | They laid 85 feet of HDPE storm pipe and set field inlet 306. RP 8-19-21  |   |                             |
| 7                                      | Misc          | •   | h HDPE storm pipe and 80 for heart storm of the heart storm of the crew informs |                             |

changed. Sent an email to Steve and Sue asking about the changes. RP

8-20-21

Informational:

8 Misc They laid 30 feet of 30 inch HP storm pipe and 130 feet of HDPE storm pipe.

They also set curb inlet 100A and field inlet 100B. Waiting on a letter from the engineer to approve the material change from RCP to HP storm pipe. RP

8-23-21

Informational:

9 Misc They laid 162 feet of 24 inch HDPE storm pipe, 35 feet of 24 inch HP storm

pipe and 105 feet of 15 inch HDPE storm pipe. They also set curb inlets 101

and 102, plus junction box 103. RP 8-24-21

## **Comments:**