CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210696 Address: 2053 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection	:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential		Michael Harkins	Not Ready	Friday, September 10, 2021
Corrective	Action Required:			
1	- - : :	 -Provide full solid block between rafters or 1-hr fire rating under roof soffit -Walls with fire separation distance less than 5 ft shall be rated 1 hour on both sides -Provide combustion air openings per code : House is insulated unable to verify items complete : : exterior bracing WSP per plan 4'-0" panels at corners : : pyro-guard is not nailed per code/per plan : 		

Comments: