

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211577
Address: 4420 SW TANZANITE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Mark Harding	Failed	Monday, September 27, 2021

Corrective Action Required:

2	Misc	-All truss hangers per plans -Nail triple girder truss together per plans ,, nail gragae triple truss. -strap plates- Dbl top plate requires 24" offset between plate breaks- see master bed exterior wall at bath wall . east wall at bath -Nail all exterior sheathing per plans - see easT and rear side of house. see cs-pf. 5th trip for all rough 4 fees due at this time.
---	------	---

Comments: