

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204843
Address: 129 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Michael Harkins	Failed	Thursday, September 30, 2021

Corrective Action Required:

1	Miscellaneous Correction	Rough in failed window nailing CS-PF still missing windows Pay outstanding fees Engineer letter foundation wall crack under beam Provide deadbolt front door Provide missing window front door & basement with flashing Provide access to jacuzzi tub motor Provide cover plate linen closet second story Provide through bolts deck beam per code Provide ledger locks per code Complete exterior trim at single car garage door Seal top of meter can & ac disconnect Seal exterior penetrations at gas line, low volt at meter can Sump shall discharge 36" from foundation
---	--------------------------	--

Comments: