

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20204958
Address: 4404 SW TANZANITE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Shawn Hoffman	Failed	Wednesday, October 06, 2021

Corrective Action Required:

1	Misc	Final grading and sod Repair unused siding bore by gas meter Seal all siding penetrations, seal along top of AC disconnect and meter can Label all dedicated receptacles in garage and unfinished basement as not GFCI protected Install lock and Secondary locking device on sliding door Secure hvac duct brackets in basement Dishwasher receptacle requires GFCI protection Secure exterior receptacle to box near AC Splash blocks at all downspout and sump pump discharge locations, min 36" distance from foundation
---	------	--

Comments: