## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20210596

Address: 2102 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

**Erosion Control** Michael Harkins Failed Thursday, October 07,

2021

Corrective Action Required:

1 DCM2 ESC DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS

DEFICIENT UNTIL ADEQUATE EROSION CONTROL PROVIDED.

INSTALLATION

MAINTAIN SILT FENCE

CLEAN GRAVEL FROM STREET

Corrective Action Required:

2 DCM2 ESC DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS

DEFICIENT UNTIL ADEQUATE EROSION CONTROL PROVIDED.

INSTALLATION - MAINTAIN GUTTER BUDDY AT CURB INLET & REMOVE SEDIMENT BUILD UP -

Corrective Action Required:

3 DCM1 ESC EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE

REQUIRED NO PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.

FURTHER INSP

- MAINTAIN SILT FENCE -

- REMOVE TRASH & SEDIMENT BUILD UP AT CURB INLET -

Corrective Action Required:

4 DCM6 ESC INSP STREET CLEAN UP REQUIRED IMMEDIATELY, AND SHALL BE COMPLETED PRIOR

DENIED STREET TO REQUESTED INSPECTION(S) BEING PERFORMED.

CLEAN UP

_	
Comm	nantc
COIIIII	iciics.