

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20210619  
Address: 3010 NW THOREAU PL, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Mark Harding	Failed	Friday, October 08, 2021

Corrective Action Required:

1	Misc	-Provide engineered solution at deck post to beam connections or use post caps and bases where beam is not notched into posts, see Eng letter ledger locks need to be from post into glulam at the bottom post, not glulam down into end of post.  NW basement room not finished( no ceiling or electrical) inside complete
---	------	--

**Comments:**