## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRCOM20191614Address:1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assembly Inspection		Robb Popp	Partial	Wednesday, October 13, 2021
Informational: 1 THIRD FLOOR		-AREAS APPROVED-		
	ional: SECOND FLOOR	BUILDING C COMPLETE		
		BUILDING B COMPLETE		
		BUILDING A COMPLETE EXCEPT ELEVA	TOR	
Informat 2		-AREAS APPROVED-		
		BUILDING C: COMPLETE		
		BUILDING B: COMPLETE		
		BUILDING A: COMPLETE EXCEPT AT ELE	VATOR	

Informational:

3 FIRST FLOOR -AREAS APPROVED-\*\*\*BUILDING C\*\*\* COMPLETE \*\*\*BUILDING B\*\*\* COMPLETE \*\*\*BUILDING A\*\*\* CORRIDOR WALLS AND CELINGS OK FOR SOFFITS TO SHAFT WALL PRE ROCK BEHIND SHOWERS ROOMS: -1016 RC AT LOBBY 1032 **RC AT CEILINGS IN** ROOMS1031-1035,1036,1037,10391055,1056,1060,1061,1062,1016,1018,1041,10 42,1046,1047,1049,1050,1052 RC AT CORRIDOR WALLS AND CEILING: 1036,1060 -SCREW PATTERN STAIRWELLS \$1,2,3 -RATED LAYER AT CEILINGS: 1016,1018,1043,1044,1046,1047,1053,1053A -SOFFIT AT CORRIDOR FROM BUILDING B TO ELEVATOR OK TO COVER -SCREW PATTERN ROOMS: 1016,1018,1032,1034,1037,1039,1040,1049-1052,1054,1056,1057,1057A,1055,10 59,1061,1062 -RATED CEILING LAYER ROOMS 1040, 1041, 1046-1052 -RATED LAYER AT CORRIDORS 1036 TO ELEVATOR, 1060 TO 1036 \*\*\*\*MCAL BUILDING\*\*\* RM 165 NORTH WALL LAYER OVER SHAFT WALL **1057 WALLS FOR ELECTRICAL GEAR RC OK ABOVE COOLER** SCREW PATTERN AT WALLS AND CEILINGS FOR COOLER RC IN CORRIDORS FIRST 16" FOR SOFFITS: CORRIDORS 167,176,177,177A,178A,169,172,173,39,42,31,34,48 PRE ROCK AT CORRIDOR SOFFITS: 176,177,177A RC ROOMS 101-147, 181, 182 RC CHANNEL ROOMS: 102-153,161-163 RC CORRIDORS 169,172,173,176,177a,177,48,39,42 -SCREW PATTERN MC UNITS 1-18 -SCREW PATTERN CORRIDORS 160, 169, 172, 173, 176, 177, 177a walls -RATED LAYER AT BATHROOM CEILINGS 101-145, 147 -SCREW PATTERN AT AT AL UNITS: 101-158, 161-163 -RC AT MC UNITS 1-18,21,24-33, 36,45,46 -RC SHARED SPACES 150-158, 162, 163, 159, 161, 162A, 170, 171, 179 -RATED LAYER AT BATHROOMS 1-18 -162 FIRST LAYER AT COLUMNS AND BEAMS, PRE ROCK FOR SOFFITS Corrective Action Required: -ADDRESS COLUMN RATING AT 162/163

4 Miscellaneous Correction **Comments:**