CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210101

Address: 329 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Not Ready Monday, October 18,

Residential 2021

Corrective Action Required:

1 Miscellaneous Support stair stringers with Simpson LS70 hangers per plan

Correction Protect NM conductors penetrating floor at kitchen island

Provide solid security blocking deck door

anchor bolts shall land in middle 1/3 the width of plate throughout Unable to verify sheathing to header nail pattern PFG portal garage

Fasten top plate to header with two rows of 16d sinkers at 2" OC per plan PFG

portal

Provide rafter ties at ceiling joist perpendicular to rafters per plan

Nail studs at intersecting wall corners per plan Provide hangers at triple joist great room @ LVL Fire block dead space behind master shower

Solid block & nail sheathing breaks office & front door Provide anchor bolts SE & NE corners bed #4 & bed # 2

Fire block soffit above wet bar Fire block soffit at game area

Provide 8 studs per plan game/ rec area

SECURE NM AT STUD ADDED UNDER RIDGE BEAM KITCHEN/GARAGE

Comments: