## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20211583

Address: 1705 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Patrick Schonfeldt Failed Wednesday, October

Residential 20, 2021

Informational:

1 Misc GARAGE PORTAL EXTERIOR OK TO COVER

Corrective Action Required:

2 Misc -Dbl top plate requires 24" offset between plate breaks - see garage East wall

- -b vent at mud room chase requires 1" clearance from combustibles
- -seal top plate penetration- master bed
- -Support IvI ridge beam at covered deck, rafter ties bottom third of rafters
- -Seal bottom plate penetration from bedroom closet 1st floor, master

shower

- -Exterior wall bracing design great room windows per plans -Nail exterior sheathing sliding glass door CS-PF per plans
- -All truss hangers per plans see garage
- -Truss V5 missing at covered deck ridge
- -4" SCH 40 steel column at pier F, W10 x 26 steel beam at basement per plans

## **Comments:**

<sup>\*\*</sup>OK TO INSULATE, REMOVE INSULATION FROM ALL CORRECTIONS\*\*