CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210628

Address: 2106 NW ASHURST DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Michael Harkins Failed Wednesday, October

Residential 27, 2021

Corrective Action Required:

1 Misc -City approved, stamped plans required on site for inspection,

2nd inspecction no truss plans.

no rear door , missing 3 windows, no gravel entrance. Fire rated walls are not correct. soffits not blocked.

this is the 8th house with the same issue.

Corrective Action Required:

2 Miscellaneous Seal floor penetrations at fireplace

Correction Seal fire blocking at fireplace

Nail studs at intersecting wall corners per plan Seal upward penetration bed 2 & dead space

Nail LIBs throughout

Provide midpoint support vertical 2" & smaller DWV throughout

Provide 4 studs at GT bearing points per roof plan

Install missing windows & SGD

Nail CS-PF exterior bracing per plan at SGD

Secure wall at basement stairs

Provide anchor bolt single car garage

Tighten anchor bolts garage
Seal upward penetrations garage

Seal fire blocking at soffits

Comments: