CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRSUBD20212196Address:1630 NE WOODS CHAPEL RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Pavement-Curb Construction		Adam Nacke	Failed	Friday, October 29, 2021
Informational:				
1	Misc	10-22-21 AN freedom concrete installed around 3/4 of all the curbs in the 7th and 8th plat. At the intersection of ne hideaway dr & ne park springs ter also the intersection of ne park springs ter and ne fuchsia dr there seems to be some elevation issues in the road at those two intersection. Talked with engineering and the plans are with in spec but we will have to wait and see after they do final grading for the road.		
Informational:				
2	Misc	10-26-21 AN All Curbs and storm inlets are now complete in the 7th and 8th plat. Had to tell contractor multiple times to make sure the white cure was put on evenly and in a timely manner.		
Corrective Action Required:				
3	Misc	10-27-21 11:00am AN. Entrance of ne park spring and made foot prints.(aro	gs dr it appears that someor und 38ft of curb)	ne walk on the wet curb
Corrective Action Required:		Entrance of Ne park springs Terr curb in front of storm inlet has NO CURE on it at all (around 26ft of curb)		
4	Misc	-	with the right of way super be ripped out and replaced. ure on it.	

Corrective Action Required:

5 Miscellaneous 10-29-21 9:12 AM found more foot prints on the curbs at the intersection of hideaway dr and park springs terr . Around 20ft of curb needs to be taken out and replaced. Pic attached (Foot prints on curb 3)

Comments: