CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211583

Address: 1705 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Patrick Schonfeldt Not Ready Friday, October 29,

Residential 2021

Informational:

1 Misc GARAGE PORTAL EXTERIOR OK TO COVER

Corrective Action Required:

2 Misc 10/29/21- MET BUILDER AT HOUSE FOR INSPECTION, BUILDER SAYS HE IS NOT

READY FOR INSPECTION

10/28/21 - NOT READY FOR INSPECTION, CORRECTIONS HAVE NOT BEEN ADDRESSED, FEES HAVE BEEN ADDED. INSULATION COVERING INSPECTION

ITEMS AS WELL

- -Dbl top plate requires 24" offset between plate breaks see garage East wall
- -b vent at mud room chase requires 1" clearance from combustibles
- -seal top plate penetration- master bed
- -Support IvI ridge beam at covered deck, rafter ties bottom third of rafters
- -Seal bottom plate penetration from bedroom closet 1st floor, master shower
- -Exterior wall bracing design great room windows per plans
- -Nail exterior sheathing sliding glass door CS-PF per plans
- -All truss hangers per plans see garage
- -4" SCH 40 steel column at pier F, W10 x 26 steel beam at basement per plans

OK TO INSULATE.	REMOVE INSUI	ATION FROM ALL	CORRECTIONS
ON TO INSULATE.	. INLIVIO V L IINJOL	A HON I NOW ALL	COMMECHONS

Comments: