

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20210101
Address: 329 NW AMBERSHAM DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Michael Harkins	Not Ready	Monday, November 01, 2021

Corrective Action Required:

1	Miscellaneous Correction	anchor bolts shall land in middle 1/3 the width of plate throughout Provide rafter ties at ceiling joist perpendicular to rafters per plan Provide anchor bolts SE & NE corners bed #4 & bed # 2 Fire block soffit above wet bar Fire block soffit at game area
---	--------------------------	---

: UNDERSLAB PLUMBING FAILED :

Comments: