CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20211583

Address: 1705 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Patrick Schonfeldt Not Ready Tuesday, November

Residential 02, 2021

Informational:

1 Misc GARAGE PORTAL EXTERIOR OK TO COVER

Corrective Action Required:

2 Misc 11/2/21 - NOT ALL CORRECTIONS ADDRESSED, SOME CEILINGS AND AREAS

HAVE BEEN ROCKED, DO NOT ROCK ANY FURTHER, NO APPROVAL HAS BEEN

GIVEN TO ROCK

10/29/21- MET BUILDER AT HOUSE FOR INSPECTION, BUILDER SAYS HE IS NOT

READY FOR INSPECTION

10/28/21 - NOT READY FOR INSPECTION, CORRECTIONS HAVE NOT BEEN ADDRESSED, FEES HAVE BEEN ADDED. INSULATION COVERING INSPECTION

ITEMS AS WELL

-Dbl top plate requires 24" offset between plate breaks - see garage East wall (see plate breaks to right of beam)

- -b vent at mud room chase requires 1" clearance from combustibles
- -Support IvI ridge beam at covered deck, rafter ties bottom third of rafters
- -Exterior wall bracing design great room windows per plans -have engineer

address, osb on interior without continuous over band/rim joist

OK TO INSULATE, REMOVE INSULATION FROM ALL CORRECTIONS

Comments: