

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20191614  
Address: 1701 SE OLDHAM PKWY, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Robb Popp	Partial	Tuesday, November 02, 2021

Informational:		
1	THIRD FLOOR	-AREAS APPROVED-
		BUILDING C COMPLETE
		BUILDING B COMPLETE
		BUILDING A COMPLETE EXCEPT ELEVATOR

Informational:		
2	SECOND FLOOR	-AREAS APPROVED-
		BUILDING C: COMPLETE
		BUILDING B: COMPLETE
		BUILDING A: COMPLETE EXCEPT AT ELEVATOR

Informational:

3 FIRST FLOOR

-AREAS APPROVED-

\*\*\*BUILDING C\*\*\*  
COMPLETE

\*\*\*BUILDING B\*\*\*  
COMPLETE

\*\*\*BUILDING A\*\*\*  
CORRIDOR WALLS AND CELINGS OK FOR SOFFITS TO SHAFT WALL  
PRE ROCK BEHIND SHOWERS ROOMS:  
-1016  
RC AT LOBBY 1032  
RC AT CEILINGS IN  
ROOMS 1031-1035, 1036, 1037, 1039, 1055, 1056, 1060, 1061, 1062, 1016, 1018, 1041, 1042, 1046, 1047, 1049, 1050, 1052  
RC AT CORRIDOR WALLS AND CEILING: 1036, 1060  
-SCREW PATTERN STAIRWELLS S1, 2, 3  
-RATED LAYER AT CEILINGS: 1016, 1018, 1043, 1044, 1046, 1047, 1053, 1053A  
-SOFFIT AT CORRIDOR FROM BUILDING B TO ELEVATOR OK TO COVER  
-SCREW PATTERN ROOMS: 1016, 1018, 1032, 1034, 1037, 1039, 1040, 1042, 1049-1052, 1054, 1056, 1057, 1057A, 1055, 1059, 1061, 1062  
-RATED CEILING LAYER ROOMS 1040, 1041, 1046-1052  
-RATED LAYER AT CORRIDORS 1036 TO ELEVATOR, 1060 TO 1036

\*\*\*\*MCAL BUILDING\*\*\*\*  
RM 165 NORTH WALL LAYER OVER SHAFT WALL  
1057 WALLS FOR ELECTRICAL GEAR  
RC OK ABOVE COOLER  
SCREW PATTERN AT WALLS AND CEILINGS FOR COOLER  
RC IN CORRIDORS FIRST 16" FOR SOFFITS: CORRIDORS 167, 176, 177, 177A, 178A, 169, 172, 173, 39, 42, 31, 34, 48  
PRE ROCK AT CORRIDOR SOFFITS: 176, 177, 177A  
RC ROOMS 101-147, 181, 182  
RC CHANNEL ROOMS: 102-153, 161-163  
RC CORRIDORS 169, 172, 173, 176, 177a, 177, 48, 39, 42  
-SCREW PATTERN UNITS 1-18, 1041-1044  
-SCREW PATTERN CORRIDORS 160, 169, 172, 173, 176, 177, 177a walls  
-RATED LAYER AT BATHROOM CEILINGS 101-145, 147  
-SCREW PATTERN AT AT AL UNITS: 101-158, 161-163  
-RC AT MC UNITS 1-18, 21, 24-33, 36, 45, 46  
-RC SHARED SPACES 150-158, 162, 163, 159, 161, 162A, 170, 171, 179  
-RATED LAYER AT BATHROOMS 1-18  
-162 FIRST LAYER AT COLUMNS AND BEAMS, PRE ROCK FOR SOFFITS  
--(2) of 3 columns complete-COMplete WRAP OF BEAM IN 162/163  
-RATED LAYER AT 149, 154, 171, 162 TO UNFINISHED COLUMN  
-MCAL 2hr wall OK

Corrective Action Required:

4 Miscellaneous

-ADDRESS COLUMN RATING AT 162/163

Correction

**Comments:**