CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20212196

Address: 1630 NE WOODS CHAPEL RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Erosion Sediment Control (ESC) Adam Nacke Failed Monday, November

Inspection 15, 2021

Corrective Action Required:

1 PW-Erosion and 10-28-21 AN Your project is in violation of the Erosion and Sediment control

Sediment Control policy. Need to get silt fencing up on all hill sides. Muddy water is flowing

into the storm drains. (Pics attached erosion 1 & 2 10-28-21)

Corrective Action Required:

2 Miscellaneous 11-12-21 9:42am AN . The erosion control needs to be address immediately..

Correction There is mud flowing into the streets and storm boxes. 8 pics attached. (

Erosion 11-12-21 1-8)

Storm boxes that were cut down and NOT repaired yet were back filled, now

allowing mud to come in on the sides of the boxes

Corrective Action Required:

3 Miscellaneous 11-15-21 AN 7th and 8th plat Welch erosion was out installing silt fence on

Correction some of the problem areas but Not all of the areas of concern were

addressed

Comments: